

GENERAL REPAIR NOTES

- ALL PARKING LOT CURBS & ADJOINING SIDEWALKS TO BE LIKE NEW PATCH & REPAIR AS REQUIRED WHERE NOT INDICATED.

2. SEE SHEET G01 FOR SPECIFICATIONS ON SEALCOAT TYPE AND APPLICATION REQUIREMENTS.



MILL & OVERLAY:
REMOVE EXISTING AGGREGATE BASE / AGGREGATE
CONCRETE AND REPLACE WITH NEW AGGREGATE
BASE / AGGREGATE CONCRETE, REF.
"TYPICAL PARKING LOT PAVEMENT REPAIR SECTION".



<u>CURB REPAIR:</u> REMOVE & REPLACE EXISTING CONCRETE CURB. REFERENCE CURB DETAILS.



PAVEMENT REPAIR: REMOVE & REPLACE PORTION OF EXISTING SIDEWALK / PAVEMENT. REFERENCE SIDEWALK

PARKING LOT REPAIR QUANTITIES

58,057 SF MILL & OVERLAY CURB REPAIR 176 LF FLATWORK 753 SF

PARKING LOT REPAIR PLAN NOTES - PLAZA

DEMO SIDEWALK & ADJOINING CURB; CONSTRUCT NEW SIDEWALK & CURB, REF. SIDEWALK DETAILS

2 DEMO CURB & STORM CURB-OPENING INLET; CONSTRUCT NEW CURB & STORM CURB-OPENING INLET 3 DEMO RAMP/WALKWAY COMPLETE; PREP FOR OVERLAY & STRIPING

4 CONSTRUCT NEW ADA RAMP 5 DEMOLEXISTING DRIVE APPROACH & CONSTRUCT NEW DRIVE APPROACH TO MATCH EXISTING.



707 n. 6th street

veritas architecture + design

kansas city, ks 66101 www.veritas-ad.com 913.624.1610

consulting engineer:

IMPROVEME

sheet issue date: 11/17/23

PARKING LOT REPAIR